



## 1 SCOPE

This document details the application of SOP 2 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### **4 SOP DETAILS**

**TYPE:** South Wales Switchgear IF4X oil switches.

**ORIGINATING REC:** SEEBOARD

**DATE:** 26/4/78

**NO. INSTALLED IN MANWEB:0**

**NO. INSTALLED IN SCOTLAND:-**

**STATUS:** Operational Ban (None on Manweb System).

**REASON:** Up to Serial No 25706, distortion of switch tank base causing bushing seal failure and oil leaks.

Also, oil leak from operating shaft bearing plate on all units up to No. 31450.

**UPDATE:**

**REMEDIAL ACTION:** Replace units up to Serial No 25706.  
Fit modified bearing with clean 'O' ring seal up to No 31450.