

# SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-012 **SOP 12**

Issue No. 1 October 2000

#### **SCOPE** 1

This document details the application of SOP 12 issued by the Electricity Association.

### 2 **ISSUE RECORD**

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

<b>Issue Date</b>	Issue No	Author	<b>Amendment Details</b>
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

### 3 **ISSUE AUTHORITY**

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



# SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-012 **SOP 12**

Issue No. 1 October 2000

### **SOP DETAILS**

**TYPE:** Long & Crawford T3GF3 & T4GF3 R.M.U.

**ORIGINATING REC:** North of Scotland Hydro-Electric Board

**DATE:** 30/6/80

NO INSTALLED IN MANWEB: 195

NO. INSTALLED IN SCOTLAND:

**STATUS:** Restriction. (All known units on Manweb inspected and found

to be in good condition. Restriction therefore does not apply in

Manweb)

**REASON:** Weld attaching main driving crank to switch operating

shaft defective in some cases, in right hand oil switch.

**UPDATE:** 

**REMEDIAL ACTION:** Inspect weld with boroscope.