



1 SCOPE

This document details the application of SOP 18 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Long & Crawford GA 11 kV Switch Fuse

ORIGINATING REC: South of Scotland Electricity Board

DATE: 15/12/81

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None on Manweb System).

REASON: Broken operating rod caused h.v. fuses to remain live when switch 'OFF'.

UPDATE:

REMEDIAL ACTION: Replace external operating rod without opening inner door of fuse chamber.