



1 SCOPE

This document details the application of SOP 19 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Metropolitan Vickers SB Switchgear

ORIGINATING REC: South Western Electricity Board

DATE: 18/6/82

NO. INSTALLED IN MANWEB: 36

NO. INSTALLED IN SCOTLAND:

STATUS: RESTRICTION (All known units in Manweb inspected and found to be in good condition therefor no restriction in Manweb.)

REASON: Failure of isolator in phase operating rod inside interrupter chamber due to tracking and lack of maintenance.

UPDATE:

REMEDIAL ACTION: Units in Manweb inspected and found in good condition.