



1 SCOPE

This document details the application of SOP 22 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Brush O & HF 11 kV Switchgear.

ORIGINATING REC: NORWEB

DATE: 3/12/82

NO. INSTALLED IN MANWEB:0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None on Manweb System).

REASON: SRBF Bushings failed due to moisture ingress.

UPDATE:

REMEDIAL ACTION: Rigorous inspection and maintenance.