



## 1 SCOPE

This document details the application of SOP 28 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Morris 11 kV O.H. Interrupter Head Isolator.

**ORIGINATING REC:** East Midlands Electricity Board

**DATE:** 9/8/84

**NO. INSTALLED IN MANWEB:** 0  
**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Restriction (None on Manweb System)

**REASON:** Interrupter head operating arm did not reset after switch closure, due to stiffness caused by corrosion between dissimilar metals.

**UPDATE:**

**REMEDIAL ACTION:** Operate as plain break isolator.