

1 SCOPE

This document details the application of SOP 29 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards

4 SOP DETAILS

TYPE: English Electric OBN9 (G) 132 kV Air Blast C.B.

ORIGINATING REC: MANWEB

DATE: 10/7/84

NO. INSTALLED IN MANWEB: 25

NO. INSTALLED IN SCOTLAND:

STATUS: No restriction in Manweb

REASON: Interrupter support porcelain fractured at base and fell during trip testing. Investigation concluded it was an isolated incident.

UPDATE:

REMEDIAL ACTION: None.