



1 SCOPE

This document details the application of SOP 31 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: GEC TYPE DDFC, DDFC4, & DDFD 11kV
R.M.U.s

ORIGINATING REC: Midlands Electricity Board

DATE: 8/2/85

NO. INSTALLED IN MANWEB:0
NO. INSTALLED IN SCOTLAND:

STATUS: None on Manweb System.

REASON: Frequent operation of oil switch and overrun of contact blades on to end stop caused resin busbar frame to fracture.

UPDATE:

REMEDIAL ACTION: Modification required.