



1 SCOPE

This document details the application of SOP 35 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Lucy 11 kV FRMU MK1

ORIGINATING REC: MANWEB

DATE: 3/12/85

NO. INSTALLED IN MANWEB: 700

NO. INSTALLED IN SCOTLAND:

STATUS: BAN on use of oil switch test prods with busbar live. .

REASON: Defective interlocks allowed oil switches to be switched to ON with test probes in position.

UPDATE:

REMEDIAL ACTION: Modification required. See P.S.B. No. 12.