



1 SCOPE

This document details the application of SOP 37 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: REYROLLE LMI, IMS 11 kV R.M.U.

ORIGINATING REC: North Eastern Electricity Board

DATE: 6/1/86

NO. INSTALLED IN MANWEB: 557

NO. INSTALLED IN SCOTLAND:

STATUS: No restriction in Manweb, except as below.

REASON: Split pin and washer missing from operating mechanism on same units, which allowed one phase switch blade to move independently.

UPDATE:

REMEDIAL ACTION: Inspection during routine maintenance. See P.S.B. No. 35.