



1 SCOPE

This document details the application of SOP 42 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Yorkshire TYKE MK2A 11 kV R.M.U.

ORIGINATING REC: Eastern Electricity Board

DATE: 8/12/86

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: None on Manweb system.

REASON: Defective corner welds allowed water ingress into cable boxes.

UPDATE:

REMEDIAL ACTION: Manufacturer changed production procedure.