

SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-043 **SOP 43**

Issue No. 1 October 2000

SCOPE 1

This document details the application of SOP 43 issued by the Electricity Association.

2 **ISSUE RECORD**

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 **ISSUE AUTHORITY**

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



SUSPENSION OF OPERATIONAL PRACTICE OPSAF-16-043 **SOP 43**

Issue No. 1 October 2000

SOP DETAILS

TYPE: Brush VSI, VTD with R&Q O.C.B.'s

ORIGINATING REC: SWEB

DATE: 11/12/86

NO. INSTALLED IN MANWEB:0 NO. INSTALLED IN SCOTLAND:

STATUS: None on Manweb system

REASON: Disruptive failure due to misaligned isolating contacts.

UPDATE:

REMEDIAL ACTION: Modifications required.