



1 SCOPE

This document details the application of SOP 44 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Cooke & Ferguson UD2 & D2 11 kV O.C.B.

ORIGINATING REC: East Midlands Electricity Board

DATE: 9/2/87

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTALND:

STATUS: None on Manweb System.

REASON: Flashover in an o.c.b. tank, after water ingress through badly fitted gasket.

UPDATE:

REMEDIAL ACTION: One off incident.