



1 SCOPE

This document details the application of SOP 46 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Ferguson Pailin ROP32 Outdoor 33 kV O.C.B.

ORIGINATING REC: SSEB

DATE: 22/5/87

NO. INSTALLED IN MANWEB: 150

NO. INSTALLED IN SCOTLAND:

STATUS: Restricted operation, (no personnel to be in outdoor compound during planned switching operations).

REASON: Water ingress through dashpot housing on top of o.c.b. caused collapse of interphase barrier, failure of contacts to open and o.c.b. to rupture, during fault clearance.

UPDATE:

REMEDIAL ACTION: Inspection required. Instructions issued. See P.S.B. No. 29.