



## 1 SCOPE

This document details the application of SOP 50 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Yorkshire YSF6 11 kV GCB V.T.

**ORIGINATING REC:** SSEB

**DATE:** 9/11/87

**NO. INSTALLED IN MANWEB:**0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** None on Manweb System

**REASON:** V.T. h.v. fuse link cap loose due to vibration. Fuse could be left in the housing on isolation.

**UPDATE:**

**REMEDIAL ACTION:** Live isolation banned. Modification required.