



1 SCOPE

This document details the application of SOP 51 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Ferguson Pailin/AEI/GEC VSLP9 33 kV O.C.B.

ORIGINATING REC: SSEB

DATE: 19/11/87

NO. INSTALLED IN MANWEB: 200

NO. INSTALLED IN SCOTLAND:

STATUS: Operational Restriction (see below)

REASON: O.C.B. failed to clear fault due to auxiliary switch remaining open.

UPDATE:

REMEDIAL ACTION: Trip circuit healthy must be confirmed before o.c.b. is put into service. Position switches must be adjusted and lubricated see P.S.B. No. 30.