



1 SCOPE

This document details the application of SOP 52 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Lucy FRMU

ORIGINATING REC: SSEB

DATE: 24/12/87

NO. INSTALLED IN MANWEB: 500

NO. INSTALLED IN SCOTLAND:

STATUS: No restriction in Manweb.

REASON: Incorrect assembly of selector shaft and lever.

UPDATE:

REMEDIAL ACTION: One off incident, but check interlock padlock holes line up, with oil switch in ON position.