



1 SCOPE

This document details the application of SOP 54 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: South Wales Switchgear Hawkgas 12 SF6 C.B.

ORIGINATING REC: South Wales Electricity Board

DATE: 22/2/88

NO. INSTALLED IN MANWEB:9

NO. INSTALLED IN SCOTLAND:

STATUS: Operational restriction (see below)

REASON: Defective latching mechanism, caused slow opening as springs were charged with c.b. closed.

UPDATE:

REMEDIAL ACTION: Do not recharge springs with c.b. in service, until modified.
See P.S.B. No. 31.