



1 SCOPE

This document details the application of SOP 55 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

| Issue Date | Issue No | Author | Amendment Details |
|--------------|----------|----------------|---|
| October 2000 | 1 | Esther Stewart | Initial Issue in New Format: 2 Page Document |

3 ISSUE AUTHORITY

| Author | Owner | Issue Authority |
|----------------|--------------|--|
| Esther Stewart | Roger Bracey | Roger Bracey Group Head, Standards |



4 SOP DETAILS

TYPE: Yorkshire TYKE MKII 11 kV R.M.U.

ORIGINATING REC: SEB

DATE: 23/2/88

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None on Manweb System)

REASON: Misaligned mechanism caused bending of centre phase contact leading to 'partial' open circuit in ON position.

UPDATE:

REMEDIAL ACTION: Modified 'bolster blocks' required.