



1 SCOPE

This document details the application of SOP 58 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Brush NSM 11 kV R.M.U.

ORIGINATING REC: EEB

DATE: 6/4/88

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None on Manweb System)

REASON: Eccentric rollers in operating mechanism allowed switch blade overtravel.

UPDATE:

REMEDIAL ACTION: Modification required. Check indicator for central location for sign of correct operation.