



1 SCOPE

This document details the application of SOP 67 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: GEC 12 kV VMX Form A Switchgear

ORIGINATING REC: EEB

DATE: 17/11/88

NO. INSTALLED IN MANWEB: 106

NO. INSTALLED IN SCOTLAND:

STATUS: No restriction in Manweb

REASON: Brass retaining ring on isolating cluster failed leading to flashover. New plated rings introduced to eliminate corrosion.

UPDATE:

REMEDIAL ACTION: All suspect rings in Manweb found to be plated.