



1 SCOPE

This document details the application of SOP 68 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Yorkshire TYKE MK1 11 kV R.M.U.

ORIGINATING REC: SEB

DATE: 14/12/88

NO. INSTALLED IN MANWEB:9

NO. INSTALLED IN SCOTLAND:

STATUS: Live operation and close access banned.

REASON: Tracking on Permali busbar support insulator in oil switch, lead to failure.

UPDATE:

REMEDIAL ACTION: Replace units in Manweb.