



1 SCOPE

This document details the application of SOP 76 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Nitran Fuse Cabinets

ORIGINATING REC: SEEBOARD

DATE: 31/3/89

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None on Manweb System)

REASON: Reduced clearance as a result of design modifications to copper bar between auxiliary fuse and red phase busbar.

UPDATE:

REMEDIAL ACTION: Modification required on Serial Nos 070-488-0730 onwards.