



1 SCOPE

This document details the application of SOP 77 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: GEC DD and DA R.M.U.s

ORIGINATING REC: MEB

DATE: 30/3/89

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None on Manweb System).

REASON: Weld on spring retaining bracket failed during operation, causing flashover.

UPDATE: 10/4/90: See SOP 96.

REMEDIAL ACTION: Inspection required.