



## 1 SCOPE

This document details the application of SOP 78 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Long & Crawford T3GF3 & T4GF3 11 kV R.M.U.

**ORIGINATING REC:** NORWEB

**DATE:** 14/4/89

**NO. INSTALLED IN MANWEB:** 195

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Operation restricted until inspected.

**REASON:** Incorrect fitting of fuse access cover gasket lead to water Ingress.

**UPDATE:**

**REMEDIAL ACTION:** Inspection required. Instruction issued for pre-inspection of outdoor switchgear for damage/corrosion, which could allow water ingress.PSB 54.