



1 SCOPE

This document details the application of SOP 84 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Ellison AP250/AP1/AP250-II 11 kV O.C.B.

ORIGINATING REC: MEB

DATE: 15/8/89

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None on Manweb System).

REASON: Defective feeder bushings caused explosion.

UPDATE:

REMEDIAL ACTION: Live operation and access banned.