



1 SCOPE

This document details the application of SOP 88 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: South Wales Switchgear 16 11 kV R.M.U.
Manweb affected.

ORIGINATING REC: MEB

DATE: 26/10/89

NO. INSTALLED IN MANWEB:0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None on Manweb system).

REASON: Roll pin fell out of linkage allowing mechanism and
indication to move from ON to OFF while switch blades
remained in ON position.

UPDATE:

REMEDIAL ACTION: All operation banned pending modification.