



1 SCOPE

This document details the application of SOP 92 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Reyrolle JKSS 11 kV R.M.U.

ORIGINATING REC: SEEB

DATE: 22/1/90

NO. INSTALLED IN MANWEB:45

NO. INSTALLED IN SCOTLAND

STATUS: Operation restricted.

REASON: Fuse link barrels with cracks around striker end caps.

UPDATE:

REMEDIAL ACTION: Units to be replaced. Instructions issued for operation. No interlock on Tee-Off Access Cover. Test Prods must not be inserted with unit live. Warning label to be fixed. See P.S.B. No. 48 and 23.