



## 1 SCOPE

This document details the application of SOP 100 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Brush L 11 kV Oil Switch

**ORIGINATING REC:** Eastern Electricity

**DATE:** 26/6/90

**NO. INSTALLED IN MANWEB:**0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Ban (None on Manweb System)

**REASON:** Failed weld on test interlock pivot caused OFF to EARTH operation to fail to earth feeder. Attempt to reset caused interlock lever to contact BB bushing.

**UPDATE:**

**REMEDIAL ACTION:** Live operation banned until modified.