



1 SCOPE

This document details the application of SOP 101 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Brush / LEL OEGMA H.V. Fuse

ORIGINATING REC: Northern Electric

DATE: 31/8/90

NO. INSTALLED IN MANWEB: 300 (Estimated)

NO. INSTALLED IN SCOTLAND

STATUS: No restriction in Manweb

REASON: After lightning storm, h.v. fuse barrel found shattered in bottom of fuse switch tank. Found to be due to damaged fuse carriage.

UPDATE:

REMEDIAL ACTION: One off incident. No action required.