



1 SCOPE

This document details the application of SOP 109 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Statter 11kV busbar earth switch (ODSA/VL)

ORIGINATING REC: SWEB

DATE: 19/6/91

NO. INSTALLED IN MANWEB: 14

NO. INSTALLED IN SCOTLAND:

STATUS: Live Operation Banned. Access Restricted.

REASON: Moisture ingress caused failure of Permali support bar.

UPDATE:

REMEDIAL ACTION: See SOP 93. All units to be replaced. Access to live substations containing this equipment should be restricted to minimum time.