



1 SCOPE

This document details the application of SOP 115 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Metropolitan Vickers/ AEI 132kv ABCB
GA6S/132 also recorded as CEGB as GA6SW4

ORIGINATING REC: SWEB

DATE: 19/11/91

NO. INSTALLED IN MANWEB:4

NO. INSTALLED IN SCOTLAND:

STATUS: Operational Restriction

REASON: Discovery of cracked interrupter support column

UPDATE:

REMEDIAL ACTION: Access to operate circuit breakers limited to short duration.
Local operation of C.B. not to be performed unless
impracticable to operate remotely. Notices to be posted to draw
attention to above.