



1 SCOPE

This document details the application of SOP 122 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Yorkshire Switchgear, FSAT Tyke II A, Switch fuse.

ORIGINATING REC: Eastern Electricity

DATE: 26/3/93

NO. INSTALLED IN MANWEB:0

NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None in Manweb)

REASON: A number of FSAT/Tyke II A switch fuses have been found to 'prop' or bounce.

UPDATE:

REMEDIAL ACTION: No Yorkshire Switchgear FSAT/Tyke II A switchfuse which has either propped or bounced may be operated live onto a suspect fault. Access to the substation shall be restricted to that required for essential operational purposes.