



## 1 SCOPE

This document details the application of SOP 123 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Merlin Gerin (YSE), 11kV Tyke II A RMU's  
(Serial No.'s RA12736 to 14444)

**ORIGINATING REC:** Eastern Electricity

**DATE:** 29/3/93

**NO. INSTALLED IN MANWEB:**0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Restriction (None in Manweb)

**REASON:** Merlin Gerin have notified of a defect in the assembly of the earth switch fitted to the ring oil switches. The earth switch blade does not fully engage.

**UPDATE:**

**REMEDIAL ACTION:** The on/off and earth switches on the Tyke II A RMU's (Serial No.'s as above) shall be operated live by means of an approved remote operating device.