



## 1 SCOPE

This document details the application of SOP 124 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** BRUSH ILSA Oil Switch (with Horizontal Bushings)

**ORIGINATING REC:** Eastern Electricity

**DATE:** 21/4/93

**NO. INSTALLED IN MANWEB:** 0  
**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Ban (None in Manweb)

**REASON:** Bolts securing the main contact bolts have been found loose. This may result in the contact block becoming detached and cause a flashover inside the tank on operation.

**UPDATE:**

**REMEDIAL ACTION:** Live operational ban on all the above switchgear. The "I" refers to Indoor units, Outdoor units are NOT affected by this SOP