



1 SCOPE

This document details the application of SOP 126 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Reyrolle OKSS Ring Main Unit.

ORIGINATING REC: ScottishPower

DATE: 19/5/93

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None in Manweb)

REASON: Three failures of bakelised paper drive bar on fuse switch due to ingress of moisture through top gaskets. Two failures cleared by fuse operation. One failure caused disruptive failure of ring main unit.

UPDATE:

REMEDIAL ACTION: No live operation of equipment. No access to substation between midday and sunset.