



1 SCOPE

This document details the application of SOP 127 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: SWS IF4X

ORIGINATING REC: East Midlands

DATE: 5/7/93

NO. INSTALLED IN MANWEB: 0

NO. INSTALLED IN SCOTLAND:

STATUS: Ban (None in Manweb)

REASON: Incident in which drive bar/blade assembly failed allowing blade to touch earth contact.

UPDATE:

REMEDIAL ACTION: No live operation of equipment. Unit to be inspected following any dead operation to check correct blade alignment and integrity of Permali drive bar and blade assembly.