



1 SCOPE

This document details the application of SOP 138 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Merlin Gerin Tyke IIA, 11kV RMU, 11kV, 21.9kA

ORIGINATING REC: Northern Ireland

DATE: 19/9/94

NO. INSTALLED IN MANWEB: 0
NO. INSTALLED IN SCOTLAND:

STATUS: Restriction (None in Manweb)

REASON: Northern Ireland Electricity, reported a disruptive failure of dry cable termination occurred during fault localisation on ring.

UPDATE:

REMEIAL ACTION: None.