



## 1 SCOPE

This document details the application of SOP 139 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Brush Falcon 11kV SF6 RMU

**ORIGINATING REC:** East Midlands

**DATE:** 20/10/94

**NO. INSTALLED IN MANWEB:** None

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Ban (None in Manweb)

**REASON:** East Midlands Electricity report: tests following a system incident indicate that one of the circuit breaker contacts was stuck in the on position when the transformer earth was applied.

**UPDATE:**

**REMEDIAL ACTION:** No live operations. Access restricted to short duration essential tasks.