



1 SCOPE

This document details the application of SOP 148 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: J & P PDB and PDB-M 11kV and 6.6kV Oil Filled Circuit Breakers

ORIGINATING REC: Manweb

DATE: 31/5/95

NO INSTALLED IN MANWEB: 1550

STATUS: Restriction

REASON:

Potential for manual trip mechanism to fail resulting in slow opening of circuit breaker.

UPDATE:

REMEDIAL ACTION:

Manual opening restricted to those circuit breakers inspected in accordance with 'Plant Service Bulletin' (No. TBA) dated 22 May 1995.

Electrical operation permitted as the electrical trip mechanism is not affected potential defect.

Manual closing is also acceptable.

Mechanical trip mechanism to be inspected at each maintenance in accordance with 'Plant Service Bulletin' (No. TBA) dated 22 May 1995.