



1 SCOPE

This document details the application of SOP 159 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: ABB " SENTINEL " RMU

ORIGINATING REC: LONDON ELECTRICITY

DATE: 08/01/96

NO. INSTALLED IN MANWEB: 49

NO. INSTALLED IN SCOTLAND:

STATUS: BAN.

REASON: London Electricity have found a fault on the mechanical interlocking/stop mechanism on two SENTINEL units. Where the fault occurs during on to off operations it may cause the switch blades to pass directly through to the earth position. The same fault appears in the reverse operation, i.e. earth to on.

UPDATE: 02/07/96 All remedial work in MANWEB complete.

REMEDIAL ACTION: Modification to ring switch mechanism.