



## 1 SCOPE

This document details the application of SOP 161 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** LUCY MK3 TRMU

**ORIGINATING REC:** SWALEC

**DATE:** 15/03/96

**NO. INSTALLED IN MANWEB:** 0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Ban (None in MANWEB).

**REASON:**

During a routine operation of one of the ring switches from ON to OFF the switch failed to complete its full travel resulting in partial contact of the main switch blades within the oil switch tank. Subsequent operations have revealed that the failure was due to friction within the moving parts of the spring charge operating handle.

**UPDATE:**

**REMEDIAL ACTION:**

All operating handles to be returned to the workshop for maintenance and testing of springs.