



## 1 SCOPE

This document details the application of SOP 210 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Lucy FRMU24 20kV Ring Main Unit Test Prods

**ORIGINATING REC:** Northern Electric

**DATE:** 18/08/98

**NO. INSTALLED IN MANWEB:** 0

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** Ban. (No 20kV gear on Manweb system)

All Lucy FRMU 20kV test prods with a metal base plate must be withdrawn from service.

**REASON:**

During over-voltage and fault location tests, a set of test prods flashed over within the tank of the ring main unit from near the top of one bushing under the metal base plate, to the side of the switch tank. As a result, the bushing was severely damaged with paper debris in the bottom of the switch tank.

**UPDATE:**

**REMEDIAL ACTION:**

As above, any Lucy FRMU 20kV test prods with a metal base plate must be withdrawn from service.