



## 1 SCOPE

This document details the application of SOP 214 issued by the Electricity Association.

## 2 ISSUE RECORD

**This is a controlled maintained document**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

## 3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards .....



#### 4 SOP DETAILS

**TYPE:** Lucy FRMU IIA Ring main units.

**ORIGINATING REC:** SEEBOARD

**DATE:** 07/09/98

**NO. INSTALLED IN MANWEB:** 700

**NO. INSTALLED IN SCOTLAND:**

**STATUS:** No restriction to be applied in Manweb.

**REASON:**

Corrosion of operating mechanism, sludge and moisture in oil.

This is an oil sludging problem associated with a particular manufacturer (not used by MANWEB), no similar problems have been experienced in Manweb. Current maintenance and oil handling procedures are considered to be sufficient to avoid problems.

See ScottishPower Operational Restriction 49.

**UPDATE:**

**REMEDIAL ACTION:**