



1 SCOPE

This document details the application of SOP 237 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE : Reyrolle type ROKSS/CC 11kV switchfuse

ORIGINATING REC: DEO

DATE: 20/07/99

NO. INSTALLED IN MANWEB:

NO. INSTALLED IN SCOTLAND:

STATUS: No restriction to be imposed in Manweb.

The following restriction to be applied by originating company:

Suspension of operation of all HV switchgear having compound type boxes which are fitted with dry terminations. Non compliant boxes to be replaced.

REASON:

Disruptive failure of ring switch cable box fitted with Raychem dry termination.

UPDATE:

REMEDIAL ACTION: