



1 SCOPE

This document details the application of SOP 255 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2000	1	Esther Stewart	Initial Issue in New Format: 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
Esther Stewart	Roger Bracey	Roger Bracey Group Head, Standards



4 SOP DETAILS

TYPE: Lucy Type FRMU 2A 11kV RMU

ORIGINATING REC: Scottish & Southern Energy

DATE: 26/07/00

NO. INSTALLED IN MANWEB:

None in this manufacturing period. Lucy have stated that SSE is the only REC that has been supplied with RMUs in the suspected range.

NO. INSTALLED IN SCOTLAND:

STATUS: Ban on Live Operation.

REASON:

QA check by Lucy on a sample batch of FRMU ring switch drive links has shown a chance of link breakage. Problem has only been identified within a specified batch of Lucy FRMU 2A 11kV RMUs manufactured between 11 April 2000 and 30 June 2000.

UPDATE:

REMEDIAL ACTION:

All live operation of ring switches prohibited.