

SUSPENSION OF OPERATIONAL PRACTICE SOP 268

OPSAF-16-268 Issue No. 1 August 2002

1 SCOPE

This document details the application of SOP 268 issued by the Electricity Association.

2 ISSUE RECORD

This is a controlled maintained document

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
August 2002	1	David Naylor	Initial Issue 2 Page Document

3 ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor	Alastair Ferguson	Eric Leavy
Senior Project Engineer	Section Head	Engineering & Transmission
	Engineering Support	Operations Manager



SUSPENSION OF OPERATIONAL PRACTICE SOP 268

OPSAF-16-268 Issue No. 1 August 2002

4	COD	DE	r a tt	C
4	30 JP	176/	AII	₩ >

TYPE: Siemens type 8DA10 circuit breakers

ORIGINATING REC: PowerGen (East Midlands)

DATE: 01/12/99

NO. INSTALLED IN MANWEB: 225

STATUS: Restriction: NO RESTRICTION IN MANWEB.

REASON: PowerGen banned the use of circuit test arrangement

due to lack of interlocks. Manweb units have additional Primary Earth indicator lamps,

padlocking and key exchange procedure. Additional

interlocking options under consideration.

UPDATE:

REMEDIAL ACTION: None required.