



**1. SCOPE**

This document details the application of SOP 295 issued by the Electricity Association.

**2. ISSUE RECORD**

**This is a controlled maintained document.**

**All copies printed via the Intranet or photocopied will be deemed uncontrolled.**

<b>Issue Date</b>	<b>Issue No</b>	<b>Author</b>	<b>Amendment Details</b>
October 2002	1	D.W. Naylor	Initial issue 2 page document

**3. ISSUE AUTHORITY**

<b>Author</b>	<b>Owner</b>	<b>Issue Authority</b>
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Eric Leavy Engineering & Transmission Operations Manager  .....

**4. SOP DETAILS**

**TYPE :** SIBA HV fuse link ref. HHE – 07/94, installed in Reyrolle JKSS 11kV RMU

**ORIGINATING REC :** Northern Ireland Electricity

**DATE :** 21/08/2002

**NO. INSTALLED IN MANWEB:** 0. Two JKSS units are installed:  
Hooton Lawn substation 04/3478/004 and  
Top-o-the-Hill substation 06/7660/001.

These units are already affected by SOP 92, and are fitted with fuse links made by other manufacturers. These units are programmed for replacement.

**NO. INSTALLED IN SCOTLAND:** 0.

**STATUS :** Restriction as required by SOP 92 remains in force.

**REASON:** SIBA HHE – 07/94 fuses were found broken in a Reyrolle JKSS unit.

This SOP as created duplicates SOP 92.

**UPDATE:**

**REMEDIAL ACTION:** Refer to SOP 92.