



1. SCOPE

This document details the application of SOP 308 issued by the Electricity Association.

2. ISSUE RECORD

This is a controlled maintained document.

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2003	1	D.W. Naylor	Initial issue 2 page document

3. ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Alastair Ferguson Section Head Engineering Support

4. SOP DETAILS

TYPE : Schneider Electric extensible RMU type RE2c
(this unit comprises an RMU coupled to an extensible switch)

ORIGINATING DNO : Defence Estates

DATE : 17 September 2003

NO. INSTALLED IN POWER SYSTEMS NORTH: 0

NO. INSTALLED IN POWER SYSTEMS SOUTH: 0

STATUS : Ban on live operation.
Restricted access to substations containing this equipment.

REASON: Suspect loose busbar connections between RMU and extensible unit.

UPDATE:

REMEDIAL ACTION: Restriction can be lifted when it has been confirmed that busbar connections between RMU and extensible unit have been tightened in accordance with manufacturer's instructions.