

1. SCOPE

This document details the application of SOP 309 issued by the Electricity Association.

2. ISSUE RECORD

This is a controlled maintained document.

All copies printed via the Intranet or photocopied will be deemed uncontrolled.

Issue Date	Issue No	Author	Amendment Details
October 2003	1	D.W. Naylor	Initial issue 2 page document

3. ISSUE AUTHORITY

Author	Owner	Issue Authority
David Naylor Senior Project Engineer	Alastair Ferguson Section Head Engineering Support	Alastair Ferguson Section Head Engineering Support

4. SOP DETAILS

TYPE : South Wales Switchgear type ID4/1 11kV oil switch

ORIGINATING DNO : East Midlands Electricity

DATE : 6 October 2003

NO. INSTALLED IN POWER SYSTEMS NORTH: 0

NO. INSTALLED IN POWER SYSTEMS SOUTH: 0

STATUS : Ban on live operation.
After 'not-live' operation, an internal inspection under a PFW is required to ensure mechanism stop plates are secured in position.

REASON: Mechanical failure of studs securing mechanism stop plate were found during routine maintenance.

UPDATE:

REMEDIAL ACTION: